

Dual-core VCO

Q1 and Q2 should be matched and in thermal contact
R3 should be in thermal contact with Q1 and Q2

Rev. 2
Davor Slamnig, 3/2021

